

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

RECEIVED
JAN 17 2002
DIVISION OF
OIL, GAS AND MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan 2001 To (mo./yr.) Dec 2001
2. DOGM File Number (Mine No): S / 43 / 0014
3. Mine Name: Henefer Red Clay
4. Mineral(s) Mined (or permitted to mine): Common Clay
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
1/4, 1/4, NE 1/4, Section 34, Township 4N, Range 4E Claims 17 & 18
1/4, 1/4, 1/4, Section, Township, Range
1/4, 1/4, 1/4, Section, Township, Range
7. Name of Operator or Company: Interpace Industries, Inc.
8. Permanent Street Address: 736 W Harrisville Rd.
City, State, Zip: Ogden, UT 84404
Phone: (801) 782-7933 Fax: (801) 782-5047
9. Company Representative (or designated operator):
Name: Aaron Hancock
Title: Director of Mining & Transportation
Business Address: P.O. Box 12118
City, State, Zip: Ogden, UT 84412
Phone: (801) 782-7933 Fax: (801) 782-5047
☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 30,000 tons

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
Material was pushed down the side of the hill with a tracked dozer.
It was then fed through a rotary screen to separate clay from the
cobbles and gravel. 30,000 tons mined (18,000 hauled, 12,000 stockpiled)
30,000 tons of gravel as waste. Increased in size by 1 acre.
5. How much **additional acreage** was disturbed during the past year? 1 acre
6. How much acreage was **reclaimed** during the past year? 0
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

8. What is the **total** disturbed acreage of entire project at years end? 6.25
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
The only activity that will take place this year is to haul the
12,000 tons stockpiled. We are working now on a large mining plan and will
submit it soon.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.**
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Aaron Hancock

Title of Operator:

Director of Mining and Transportation

Signature of Operator:



Date:

Jan 16, 2002

RECEIVED

JAN 17 2002

DIVISION OF
OIL, GAS AND MINING



✓ 5/43/014
m/49/006

736 HARRISVILLE ROAD, OGDEN, UTAH 84404 801-782-7933

January 16, 2002

State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
1594 W North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, UT 84114-5801

Dear Sirs,

Enclosed you will find mining reports for our two clay mines we operate in Henefer and Lehi. Please make note that the legal description of the mine at Henefer has been incorrect for years. The correct description is N.E. ¼ of section 34 T4N R4E. The mine has not moved, but years ago an employee here put the description of another property Interpace owned in Henefer in error on a report.

If you have any questions please feel free to call me at (801)782-7933.

Thanks,

A handwritten signature in dark ink, appearing to read 'Aaron Hancock', is written over a faint, larger signature.

Aaron Hancock
Director of Mining and Transportation

RECEIVED
JAN 22 2002
DIVISION OF
OIL, GAS & MINING